


Documentatie tehnica robot de gazon RURIS Rx1000, Rx1500



Producător motoutilaje

Documentatie tehnică

Nr. Crt	Denumire produs	Product name	Cod comanda
1	suport conector incarcare(stanga)	charging copper stent(left)	psrx1000-1-1
2	conector incarcare	charging copper	psrx1000-1-2
3	clema	wire clamp	psrx1000-1-3
4	surub	screw	psrx1000-1-4
5	cablu conector icarcare	the four core power line	psrx1000-1-5
6	suport conector incarcare(dreapta)	charging copper stent(right)	psrx1000-1-6
7	surub	screw	psrx1000-1-7
8	capac exterior	outer cover	psrx1000-1-8
9	surub	bolt	psrx1000-1-9
10	suport amortizor	collision stents	psrx1000-1-10
11	surub	screw	psrx1000-1-11
12	amortizor	collision rubber connector	psrx1000-1-12
13	suport amortizor	collision stents	psrx1000-1-13
14	magnet detectare coliziune	collision detection magnet	psrx1000-1-14
15	surub	screw	psrx1000-1-15
16	buton	scram button	psrx1000-1-16
17	arc	a reset spring	psrx1000-1-17
18	surub	screw	psrx1000-1-18
19	clema	clamp plate	psrx1000-1-19
20	comutator	quick stop switch signal line	psrx1000-1-20
21	manson	seal strip	psrx1000-1-21
22	maner	carrying	psrx1000-1-22
23	cheie pornire	start key	psrx1000-1-23
24	oring	o-ring	psrx1000-1-24
25	cablu	start key signal line	psrx1000-1-25
26	clema	fixed plate	psrx1000-1-26
27	protectie cheie	safety key hole seal	psrx1000-1-27
28	capac	control key cover plate	psrx1000-1-28
29	manson	programming port sealing strip	psrx1000-1-29
30	surub	screw	psrx1000-1-30
31	magnet	magnet	psrx1000-1-31
32	panou control	the lcd panel rack	psrx1000-1-32
33	garnitura	lcd panel rack seal strip	psrx1000-1-33
34	placa de control	key pad	psrx1000-1-34
35	protectie switch on/off	power switch waterproof cap	psrx1000-1-35
36	switch on/off	main engine power switch wire	psrx1000-1-36
37	acumulator	battery pack	psrx1000-1-37
38	garnitura	battery pack seal ring	psrx1000-1-38
39	capac acumulator	battery pack cover plate	psrx1000-1-39
40	placa de control principala	the main control pcb	psrx1000-1-40

Producător motoutilaje

Documentatie tehnică

41	cablu alimentare motor	mowing motor power cable	psrx1000-1-41
42	cablu alimentare placa de control	keypad layout	psrx1000-1-42
43	cablu alimentare	battery pack plug-in adapter	psrx1000-1-43
44	garnitura fixare	male insert fixed gasket	psrx1000-1-44
45	conector baterie	battery adapter	psrx1000-1-45
46	placa	plate	psrx1000-1-46
47	motor	engine	psrx1000-1-47
48	oring	o-ring	psrx1000-1-48
49	capac motor	engine cover	psrx1000-1-49
50	surub	fastener assembling unit	psrx1000-1-50
51	pin cilindric	elastic cylindrical pin	psrx1000-1-51
52	ax transmisie	driving shaft	psrx1000-1-52
53	roata spate	wheel assembly	psrx1000-1-53
54	piulita	nut	psrx1000-1-54
55	capac roata spate	wheel cap	psrx1000-1-55
56	placa control motor	motor drive plate	psrx1000-1-56
57	protectie	the knife dish cover	psrx1000-1-57
58	surub	screw	psrx1000-1-58
59	piulita	the blade nut	psrx1000-1-59
60	disc lame	the blade disk	psrx1000-1-60
61	lama	blade	psrx1000-1-61
62	capac roata fata	universal wheel	psrx1000-1-62
63	siguranta	return spring	psrx1000-1-63
64	saiba	washer	psrx1000-1-64
65	bucsa	bush	psrx1000-1-65
66	roata fata	wheel	psrx1000-1-66
67	surub	screw	psrx1000-1-67
68	capac	universal wheel dust cover	psrx1000-1-68
69	ax rota	driving shaft	psrx1000-1-69
70	saiba	washer	psrx1000-1-70
71	clema	lift follow-up bracket	psrx1000-1-71
72	magnet	lifting magnet	psrx1000-1-72
73	carcasa inferioara	base	psrx1000-1-73
74	bucsa	bush	psrx1000-1-74
75	senzor detectare perimetru	lifting detection board	psrx1000-1-75
76	placa detectare perimetru	boundary detection board	psrx1000-1-76
77	cablaj	boundary signal line	psrx1000-1-77
78	clema	clip	psrx1000-1-78
79	protectie	protection	psrx1000-1-79
80	clema	wire clamp	psrx1000-1-80
81	bucsa	bush	psrx1000-1-81

Producător motoutilaje

Documentatie tehnică

82	oring	o-ring	psrx1000-1-82
83	garnitura	main engine seal	psrx1000-1-83
84	piulita	self-locking nut	psrx1000-1-84
85	saiba	washer	psrx1000-1-85
86	cuplaj	coupling	psrx1000-1-86
87	carcasa ajustare motor	mowing motor barrel	psrx1000-1-87
88	motor	mowing motor	psrx1000-1-88
89	surub	screw	psrx1000-1-89
90	saiba	washer	psrx1000-1-90
91	placa ajustare	adjusting plate	psrx1000-1-91
92	ansamblu senzor detectie coliziuni	collision detection board assembly	psrx1000-1-92
93	saiba	washer	psrx1000-1-93
94	capac stanga	cover left	psrx1000-1-94
95	carcasa superioara	upper cover	psrx1000-1-95
96	capac dreapta	cover right	psrx1000-1-96
97	piulita	hexagonal self-locking nut	psrx1000-1-97
98	surub	bolt	psrx1000-1-98
99	arc	lock-up spring	psrx1000-1-99
100	cablaj senzor ploaie	rain signal line	psrx1000-1-100
101	resort reducere zgomot	noise reduction spring	psrx1000-1-101
102	ansamblu avertizare	warning light & buzzer assembly	psrx1000-1-102
103	capac	cover	psrx1000-1-103
104	vizor	viewfinder	psrx1000-1-104
105	capac	cover plate	psrx1000-1-105
106	maneta relare inaltime	height adjustment handle	psrx1000-1-106
107	placa	plate	psrx1000-1-107
108	surub	screw	psrx1000-1-108
109	capac protectie	upper cover of charging base	psrx1000-1-109
110	cover	cover	psrx1000-1-110
112	cablu incarcare	charging cable	psrx1000-1-112
113	placa comanda baza incarcare	charging base control panel	psrx1000-1-113
114	carcasa placa comanda	charging stand circuit board holder	psrx1000-1-114
115	conector incarcare	charging connector	psrx1000-1-115
116	arc	spring	psrx1000-1-116
117	arc	spring	psrx1000-1-117
118	saiba	washer	psrx1000-1-118
119	conector	charging station boundary signal line	psrx1000-1-119
120	stand incarcare	charging base	psrx1000-1-120
121	alimentator	power supply unit	psrx1000-1-121
122	cablu alimentare	power cord for charging base	psrx1000-1-122

RURIS

Producător motoutilaje



Documentatie tehnică

Craiova, ROMÂNIA